

ABSTRACT

A method for optimizing performance of an apparatus includes interrogating at least one part of the apparatus to obtain information about the at least one part. Once the at least one part is interrogated, instructions for

5 optimizing at least one operation of the apparatus is determined based on the obtained information about the at least one part. Next, the instructions are applied to the at least one operation of the apparatus to optimize the performance.